


boutmy

SENS

LES BUTÉES " H "



Référence	d	h	g	M	I1	Charge Max daN En compression
H 10/8 M4	10	8	M4	4,5	10	2
H10/10 M4	10	10	M4	8	10	2
H 15/15 M6	15	15	M6	12	18	4
H20/15 M6	20	15	M6	14	18	10
H 30/20 M8	30	20	M8	22	23	15
H 40/30 M8	40	30	M8	25	23	25
H 40/50 M8	40	50	M8	20	23	30
H 57/45 M8	57	45	M8	25	23	40
H 57/44/45 M10	57	45	M10	44	28	75
H 60/60 M10	60	60	M10	49	28	150
H 95/80 M16	95	80	M16	80	41	400